



Temperature

Centigrade °C	=	Fahrenheit
-273.15	=	-459.67
-250	=	-418
-200	=	-328
-150	=	-238
-100	=	-148
-50	=	-58
-40	=	-40
-30	=	-22
-20	=	-4
-10	=	14
0	=	32
5	=	41
10	=	50
15	=	59
20	=	68
25	=	77
30	=	86
35	=	95
40	=	104
45	=	113
50	=	122
55	=	131
60	=	140
65	=	149
70	=	158
75	=	167
80	=	176
85	=	185
90	=	194
95	=	203
100	=	212

To convert centigrade to fahrenheit °C ÷ 5 = x9 = +32 = 1°f
 To convert fahrenheit to centigrade °F - 32 = ÷9 = x5 = 1°c